

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,149,398 B2
APPLICATION NO. : 10/759680
DATED : December 12, 2006
INVENTOR(S) : Solheid et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 6, line 27: "frame are not" should read --fram 20 are not--

Col. 9, lines 48-49: "tab **181** a helps maintain the cable in passage **170**. Tab **181** a also" should read --tab **181a** helps maintain the cable in passage **170**. Tab **181a** also--

Col. 10, line 3: "lower comer guide" should read --lower corner guide--


Col. 10, line 8: "upper comer guide" should read --upper corner guide--

Col. 21, line 38, claim 1: "on the tight" should read --on the right--

Col. 22, line 49, claim 9: "holding at leant one" should read --holding at least one--

Signed and Sealed this

Sixteenth Day of October, 2007



JON W. DUDAS
Director of the United States Patent and Trademark Office